# PART NUMBER WTC-1307-1

This Wire Termination tool can be used to terminate wires for Zierick **Part Number 1307** (Surface Mount Insulation Piercing Crimp Terminal) in low volume or in the field (Figure 1).

**Crimping Instructions:**

- Place wire over the SMT Crimp Terminal using slight pressure. Align the Notch on the side of the anvil with the 'Fingered'/tall side of the part (Figure 2).
- Squeeze the Tool handle to push the terminal down until hand tool releases (Figure 3).

**Crimp Hand Tool Part Numbers:**

- WTC-1307-1



**1307 Hand Tool Orientation and Edge Distance**



Figure 1: WTC-1307-1 Termination Tool



Figure 2: Wire Placement in Tool



Figure 3: Wire Crimped in Hand Termination Tool