



PART NUMBER WTW-1293

This Wire Termination tool can be used to terminate wires for Zierick **Part Number 1293** (Surface Mount Insulation Piercing Terminal) in low volume or in the field (Figure 1).

Crimping Instructions:

- Place wire over the SMT Crimp Terminal using slight pressure.
- Place wire with Crimp Terminal into the Wire Termination Tool as shown in the picture (Figure 2).
- Squeeze the Tool handle to crimp the terminal and terminate the wire into the Crimp Terminal (Figure 3).

Crimp Hand Tool Part Number:

- WTW-1293



Figure 1: WTW-1293 Termination Tool




Figure 2: Wire Placement in Tool




Figure 3: Maximum clearance from the edge of the PCB